

Application Note – Unitronics touchscreen permanently on

GENERAL RELEASE

All Unitronics touchscreen OPLC's with silver bezel.

Symptoms

The OPLC boots up into INFO mode and will not run the program or fails to respond to any area of the touchscreen being pressed.

Cause

The OPLC thinks that someone is permanently pressing the touchscreen, this is caused by a build up of dirt or foreign material between the silver bezel and the touchscreen, possibly by having the screen constantly wiped clean.

Remedy

The problem can be rectified by removing the dirt particles. The silver bezel can be removed by gently levering the bezel, taking care not to let any sharp tools used for this purpose to impact on the screen itself. Removal of the bezel does not compromise the OPLC's IP rating. Thoroughly clean the surface of the screen with a soft cloth and warm soapy water. Replace the bezel.

System bits and registers

While the touchscreen itself may be disabled the programming software should still be able to monitor the OPLC system registers and bits. The following registers and bits may assist in diagnosing where the problem is. The screen co-ordinates origin (0,0) is at the top left hand corner of the screen.

SB 16	Touchscreen Active
SI 6	Current key pressed
SI 40	Touchscreen is being touched- X coordinates If the screen is touched, SI 40 shows the current location on the X axis.
SI 41	Touchscreen is being touched-Y coordinates If the screen is touched, SI 41 shows the current location on the Y axis.

Tony Spearing
Technical Manager
28 October 2010